



MMCZ-RFQ  
#2025-513

**Address:** 90 Mutare Road | **Telephone 1:** +263 242 487200 | **Telephone 2:** +263  
242 487201-4 | **Website:** [www.mmcz.co.zw](http://www.mmcz.co.zw)

**To All Suppliers**

**Publication Date:** 2025-  
06-20

**Closing Date:** 2025-06-24

**Closing Time:** 11:00:00

**Return Quotation to:**

Procurement Management  
Unit

MMCZ Building, 90 Mutare  
Road

[proc@mmcz.co.zw](mailto:proc@mmcz.co.zw)

Item	Description of Requirements	Requirement Specification	Quantity
1	REPAIR AND REPAINT DAMAGED WALLS AT STAIRCASES LEADING TO THE REAR EXIT DOOR.	WALLS DAMAGED BY MOISTURE NEEDS REPLASTERING AND REPAINTING. MMCZ HEAD OFFICE	1.00

**NB:** Your Quotation Must Be In USD.

**NB:** Bidders are invited for a compulsory supplier site meeting at MMCZ Head Office 90 Mutare Road Msasa Harare on 2025-06-23 at 11:00:00.

**INSTRUCTIONS AND CONDITIONS**

- VALID TAX CLEARANCE CERTIFICATE
- PRICE VALIDITY OF 30 DAYS
- PAYMENT AFTER DELIVERY

**REQUIRED DOCUMENTS**

- VALID TAX CLEARANCE
- PRAZ REGISTRATION CERTIFICATE

